Approved For Release 2003/01/24 - CIARDP63-00313A000600100046-5

IDEA-0967

18 December 1962

	MEMORANDUM FOR:	Acting Assistant Director, OSA-DD/R		
	SUBJECT :	355 Engine Difficulties		
	REFERENCE : 25X1A	Dispatch No. FCWT-0599, from Chief of B Subject Monthly Commander's Re November 1962; Para A. 1, Comment Conce Lack of Recommendations on Engine Prob1	port rning	
	1. Prior to departure from the undersigned with LAC and PW personnel throughly discussed this problem with the Chief of Base. The following conclusions were reached:			
	a. P & W and LAC would continue research on an improved P and D Valve to improve and smooth combustion, thereby reducing vibration			
	b. Ar flame out p	eduction in EGT in climb is required to cossibility 25X1D		
	2. Since my return to Headquarters several cables have been exchanged with contractors concerned, reference the above problem. has been Info Addee on all these cables. 25X1A			
25X1A		a. Additionally a summary with progress to date will be this date.		
			25X1A	
		Maintainance Officer OSA=DD/R	I	